

# SPEC SHEET + MEASUREMENTS

*Brooks Brothers*

Brooks Brothers® Tall Wrinkle-Free Stretch Pinpoint Shirt.

TBB18000

## Product photo



This iconic dress shirt combines a little bit of stretch with a higher back yoke for a classic fit. A premium wrinkle-free treatment process means effortless style and a sharp, professional finish all day long.

- 4.4-ounce, 97/3 cotton/spandex fine yarn count
- Taped seams
- Button-down collar
- Left chest pocket
- Pearlized buttons
- Rounded, single-button cuffs
- Rental-friendly

## CARE INSTRUCTIONS

Machine Wash Warm With Like Colors. Only Non-Chlorine Bleach If Needed. Tumble Dry Low. Remove Promptly And Hang. Warm Iron If Needed.

## Sketches



front



back

# SPEC SHEET + MEASUREMENTS

*Brooks Brothers*

Brooks Brothers® Tall Wrinkle-Free Stretch Pinpoint Shirt.  
TBB18000

## PRODUCT MEASUREMENTS

	LT	XLT	2XLT	3XLT	4XLT
Body Length at Back	33	33 1/2	34	34 1/2	35
Chest	24	26	28	30 1/2	33 1/2
Sleeve Length from Center Back	37 1/2	38 1/4	39	39 3/4	40 1/2
Neck Circumference	17 1/2	18 1/4	19	19 7/8	20 7/8
Chest Pocket Height	5	5	5	5	5 1/4
Chest Pocket Width	4 5/8	4 5/8	4 5/8	4 5/8	4 7/8

**Body Length at Back:** Measured from high point shoulder to finished hem at back.

**Chest:** Measured across the chest one inch below armhole when laid flat.

**Sleeve Length from Center Back:** Measure from Center Back neck to shoulder point to sleeve hem.

**Neck Circumference:** Measure from center of button to end of buttonhole along the center of the collar stand.

**Chest Pocket Height:** Measure from top to bottom at center.

# SPEC SHEET + MEASUREMENTS


*Brooks Brothers*

Brooks Brothers® Tall Wrinkle-Free Stretch Pinpoint Shirt.  
TBB18000

## SIZE CHARTS

	LT	XLT	2XLT	3XLT	4XLT
Chest	41-43	44-46	47-49	50-53	54-57
Neck	16 - 16 1/2	16 1/2 - 17	17 - 17 1/2	17 1/2 - 18	18 - 18 1/2
Arm	36 1/2	38	39	40	41

## HOW TO MEASURE



**Neck** Measure around the fullest part of the neck at the base.  
**Chest Width** Measure under the arm and around the fullest part of the chest with arms down, keeping tape horizontal. **Arm** Place hand on hip. Start at the center of the back of the neck and measure across the shoulder, to the elbow, and then down to the wrist.

## COLORS



Cobalt Blue



Deep Black  
PMS BLACK  
C



Newport Blue  
PMS 7681C



White